

To: Carey, Douglas@Waterboards[douglas.carey@waterboards.ca.gov]
Cc: Greg Reller[gr@burlesonconsulting.com]; Cory Koger[Cory.S.Koger@usace.army.mil]; Wirschafter, Joshua[Wirschafter.Joshua@epa.gov]; Brown, Anthony R (RM[anthony.brown@bp.com]; Cohen, Adam[Adam.Cohen@dgsllaw.com]; 'Mike Johnson'[mike.johnson@copperenv.com]; Lombardi, Marc (marc.lombardi@amecfw.com)[marc.lombardi@amecfw.com]; Stetler, Chris@Waterboards[Chris.Stetler@waterboards.ca.gov]; Ferguson, Scott@Waterboards[scott.ferguson@waterboards.ca.gov]; Tom Bloomfield (tbloomfield@thegallaghergroup.com) (tbloomfield@thegallaghergroup.com)[tbloomfield@thegallaghergroup.com]; Coupe, David@Waterboards[David.Coupe@waterboards.ca.gov]; Kouyoumdjian, Patty@Waterboards[patty.kouyoumdjian@waterboards.ca.gov]
From: Deschambault, Lynda
Sent: Fri 4/14/2017 12:49:46 AM
Subject: RE: Leviathan Weekly Update

Thank you.

Tony/Mike, please incorporate these in to your revised weekly report with appropriate title.

As noted the text should Include approximate estimates of flow rates, and volumes.

Please include the before and after staff readings

Thank you.

From: Carey, Douglas@Waterboards [mailto:douglas.carey@waterboards.ca.gov]
Sent: Thursday, April 13, 2017 3:34 PM
To: Deschambault, Lynda <Deschambault.Lynda@epa.gov>
Cc: Greg Reller <gr@burlesonconsulting.com>; Cory Koger <Cory.S.Koger@usace.army.mil>; Wirschafter, Joshua <Wirschafter.Joshua@epa.gov>; Brown, Anthony R (RM <anthony.brown@bp.com>; Cohen, Adam <Adam.Cohen@dgsllaw.com>; 'Mike Johnson' <mike.johnson@copperenv.com>; Lombardi, Marc (marc.lombardi@amecfw.com) <marc.lombardi@amecfw.com>; Stetler, Chris@Waterboards <Chris.Stetler@waterboards.ca.gov>; Ferguson, Scott@Waterboards <scott.ferguson@waterboards.ca.gov>; Tom Bloomfield (tbloomfield@thegallaghergroup.com) (tbloomfield@thegallaghergroup.com) <tbloomfield@thegallaghergroup.com>; Coupe, David@Waterboards <David.Coupe@waterboards.ca.gov>; Kouyoumdjian, Patty@Waterboards <patty.kouyoumdjian@waterboards.ca.gov>
Subject: RE: Leviathan Weekly Update

Email 3 of 3

-

Lynda,

As requested, attached are a few additional photos of the Pond 4 (near HDS) area taken by Water Board personnel between April 6 and April 11, 2017. The time and date stamp on the photos is helpful to follow the situation as originally observed on April 6 through the April 11, 2017 standpipe repair. I'll send photos in three parts as some firewalls are very restrictive.

Photo 170406 tz 013 is when the damaged standpipe in Pond 4 was first observed by Water Board personnel. Note approximate staff reading.

Photos 170407 tz 002, 003 and 005 are during initial repair activities.

Photo 170407 tz 046 is of failed initial repair.

Photo 170411 tz 015 is of final repair. Note staff reading.

Note: During the storm that passed through the area April 6 through April 9, 2017, approximately 2 to 3 inches of precipitation (liquid) fell on the site.

Douglas Carey, P.G.

Senior Engineering Geologist

Leviathan Mine

Regional Water Quality Control Board, Lahontan Region

2501 Lake Tahoe Blvd.

South Lake Tahoe, CA 96150

(530) 542-5468

douglas.carey@waterboards.ca.gov